






Atera[®] SIGNO

VW
T5 2003–



nur bei / only for Part-No.: 045 149



- | | | |
|------------|-------------|-------------------|
| 1- 074 137 | 7- 092 044 | 14- 095 218 |
| 2- 093 357 | 8- 087 866 | 14a- 092 609 |
| 3- 092 034 | 9- 087 656 | 15- 093 439 |
| 4- 088 184 | 10- 087 866 | 16- 093 710 |
| 5- 092 043 | 11- 087 909 | nur bei/only for |
| 6- 092 045 | 12- 092 181 | Part-No.: 045 149 |
| | | 17- 092 043 |
| | | 18- 093 137 |
| | | 19- 092 071 |

10

Atera[®]
MADE IN GERMANY

Atera GmbH
Postfach 2240
D-88192 Ravensburg
Telefon 07 51 - 76 04-0
Telefax 07 51 - 76 04-76
E-Mail: info@atera.de


Atera[®] SIGNO

VW
T5 2003–


Zusatzbügel / additional carrier bow

Part-No. : 044 149

Part-No. : 045 149



Part-No. : 044 149



Part-No. : 045 149

